


, 14

A Batch Dissolver







FIGURE 4



A Schematic for Continueous Production of the MEA Complex of Copper Solution

Copper Dissolution vs Air Flow Rate Continuous @ pH = 9.8




FIGURE 6

Copper Dissolution vs. Air Flow Rate Continuous @ pH = 9.5




FIGURE 7

C pper Dissolution Rate vs. pH Continuous @ 6.0 SCFH Air Flow Rat

